

HILLVIEW

ATV middle class (to 200cc), BUGGY and JEEP middle class

Violation	Amount of penalty	More information
Plastics and elements		
Small plastic elements <i>/*in case of cosmetic damage, no need for replacement -50% of the amount of the penalty/</i>	60EUR*	Mask, mirror, protectors, handlebar consoles, plastic stop
Large plastic elements* <i>/*in case of cosmetic damage, no need for replacement -50% of the amount of the penalty/</i>	130EUR*	All rear / front plastic and panels, mask BUGGY plastic leg positioning
	100EUR*	Plastic leg positioning
	55EUR	Backrest
Headlight / Stop	130EUR / 70EUR	
Standnumber	65EUR*	
Brake levers	55EUR	For broken/bent lever, complete set replaced, with incl. pump
Damages to other small plastics/elements	45EUR	
Drive and steering		<i>In the case of impacts caused by the fault of the user of the machine, including impacts due to leaving the road/drift/improper speed and others</i>
Steering		
Upper steering rod	45EUR	In case of bent or broken steering rod
Tie rod fasteners	25EUR	In case of damaged elements
Steering rod	110EUR	In case of overturning the vehicle

HILLVIEW

Drive		
Wheelshaft	160EUR	
Universal joints (Cardan)	130EUR	
Control arm	600EUR	
Steering rod*	70EUR	<i>*steering rod end -50%</i>
Rear axle	180EUR	
Flat tire	55EUR	<i>Flat tire as a result of an impact/unlawful departure from the road and others</i>
Warped rim	55EUR	<i>Warped rim as a result of an impact/unlawful departure from the road and others</i>
Bent metal load-bearing and non-load-bearing components and pipes	55-110EUR	In case of impact on the structural part of the machine
Frame	410EUR	In case of impact on the structural part of the machine

Up to 1300EUR penalty

Maximum penalty amount 1300EUR in case of impacts and damages that lead to long-term damage and/or total damage to the machine

HILLVIEW

ATV and BUGGY higher class, ATV middle class (400cc), 4x4 electric ATV / scooter

Violation	Amount of penalty	More information
Plastics and elements		
Small plastic elements <i>/*in case of cosmetic damage, no need for replacement -50% of the amount of the penalty/</i>	65EUR*	Mask, mirror, protectors, handlebar consoles, plastic stop
Large plastic elements* <i>/*in case of cosmetic damage, no need for replacement -50% of the amount of the penalty/</i>	170EUR*	All rear / front plastic and panels, mask BUGGY plastic leg positioning
	100EUR*	Plastic leg positioning
	95EUR*	Backrest
	210EUR	Rood
Headlight / Stop	180EUR* / 70EUR	*for BUGGY - 50%
Standnumber	70EUR	
Brake levers	75EUR	For broken/bent lever, complete set replaced, with incl. pump
Damages to other small plastics/elements	10EUR	
Drive and steering		<i>In the case of impacts caused by the fault of the user of the machine, including impacts due to leaving the road/drift/improper speed and others</i>
Steering		
Upper steering rod	75EUR	In case of bent or broken steering rod
Tie rod fasteners	30EUR	In case of damaged elements

HILLVIEW

Steering rod	180EUR	In case of overturning the vehicle or strong frontal impacts
Rake	260EUR	
Rake tip	100EUR	
Drive		
Wheelshaft	170EUR / 285EUR	ATV / BUGGY
Universal joints (Cardan)	130EUR / 2660EUR	ATV / BUGGY
Control arm	80EUR / 160EUR	ATV / BUGGY
Shankel	90EUR / 210EUR	ATV / BUGGY
Flat tire	60EUR	<i>Flat tire as a result of an impact/unlawful departure from the road and others</i>
Warped rim	75EUR	<i>Warped rim as a result of an impact/unlawful departure from the road and others</i>
Bent metal load-bearing and non-load-bearing components and pipes	55-110EUR	In case of impact on the structural part of the machine
Frame	210EUR	In case of impact or deformation of the machine's structural frame

Up to 1800EUR penalty

Maximum penalty amount 1800EUR in case of impacts and damages that lead to long-term damage and/or total damage to the machine